



5/32" holes to start square cutouts

5/32" hole for machine screw

1/16" hole for escutcheon pin



5/16" holes to start square cutouts

3/16" holes to start square cutouts

